

02/20/2024

Safety Notice

RECALL SUMMARY SAFETY NOTICE

Name of Product: Vacuum tool

Hazard: Overheating safety concern

Remedy: Replace. We are initiating a FREE Replacement Program to ensure you have the best version for servicing Absen products, irrespective of your tool's warranty status.

